

A Better Drill Steel Support!


FITS EPIROC®
D50, D60, D65's

What is the problem with the factory Drill Steel Support?

Problem: After installing the O.E.M. 3222 3300 90 Drill Steel Support Half the threads in the support seize to the piston rod that drives them almost immediately.


Solution: We made the support into a replaceable two piece system. Why throw away your piston every time your jaw wears out? With 425's two piece system you just replace the bottom plate when your piston eventually wears out.

Our top jaw is made from identical to factory material and is heat treated identically.



Our bottom plate is 2x's thicker than factory. This allows for more engagement of the piston rod thread into the backing plate.


425 Manufacturing is an Aftermarket Parts Manufacturer and not affiliated or authorized by any of the listed manufacturers. Our parts are manufactured in our facility in Rockford, IL - U.S.A.



**425 P/N 3235
2 Piece Assembly**



**425 P/N 3153
EPIROC® OEM Style
P/N 3222 3300 90**



**425 P/N 3388
2 Piece Assembly**



**425 P/N 3775
EPIROC® OEM Style
P/N 3222 3208 95**



2500 Harrison Ave, Rockford, IL 61108

Phone 815-904-6363

E-mail: Sales@425mfg.com

www.425DrillRigParts.com