


A Better Drill Steel Support!

FITS EPIROC®
D50, D60, D65's

What is the problem with the factory Drill Steel Support?

Problem: After installing the O.E.M. 3222 3300 90 Drill Steel Support Half the threads in the support seize to the piston rod that drives them almost immediately.

Solution: We made the support into a replaceable two piece system. Why throw away your piston every time your jaw wears out? With 425's two piece system you just replace the bottom plate when your piston eventually wears out.




425 Manufacturing is an Aftermarket Parts Manufacturer and not affiliated or authorized by any of the listed manufacturers. Our parts are manufactured in our facility in Rockford, IL - U.S.A.



425 P/N 3235
2 Piece Assembly



425 P/N 3153
EPIROC® OEM Style
P/N 3222 3300 90



425 P/N 3388
2 Piece Assembly



425 P/N 3375
EPIROC® OEM Style
P/N 3222 3208 95



2500 Harrison Ave, Rockford, IL 61108

Phone 815-873-7066

E-mail: Sales@425mfg.com

www.425DrillRigParts.com